

Protective lead screw cover of neoprene impregnated nylon

Interchangeable X, Y and Z axis motors

Convenience service panel

Spindles closely coupled to Z-axis ways to maintain spindle location accuracy

1/2" capacity, 24,000 RPM continuous-duty spindles

Tri-Mill  
KENNARD

Continuously supported X and Y ways for accuracy

Massive 2-ton welded steel base for stability

